CHARACTERISTIC

1. Accurate temperature measurement,easy conversion of Celsius and Fahrenheit, test data read directly.
2.Automatic shutdown function, with setting the shutdown time. When the measured temperature of the sensor is less than 100 °C, the thermometer starts timing and automatically shuts down at the setting time.The thermometer automatically shuts down.
3. Temperature correction function.
4. Password function,to prevent parameters from being modified.5. "MAX HOLD" maximum temperature hold function.6. With external K-type sensor function

PARAMETERS

III. Specifications

Model	192
Measurement range	(0-600)°C
Accuracy	±3°C (300-500°C)
Resolution ratio	1°C
Sensor	K-Thermocouple (NiCr-NiSi)
LCD display	" 🔋 " for low battery " 1 " for sensor damaged
The range of automatic shutdown time	10~60min / automatic shutdown
Battery life	9V battery , ≥150h
Dimensions	L160 x H43 x W82mm
Weight	0.26kg
Operating temperature	0°~40°C