




SCHEMATIC DIAGRAM




WELDING DETAILS

















press the switch turn on, and press again, turn off

