

Wider Monitoring Range

Temperature measuring range from -40°C to $+80^{\circ}\text{C}$ and humidity measuring range from 0 to 99.9%RH for broad use in various devices

Power Supply: 3.3 – 5.2V DC (5V recommended)

Temp. Measuring Range: -40°C ~ $+80^{\circ}\text{C}$

Humidity Measuring Range: 0 ~ 99.9%RH

Temp. Sensor Type: Resistive

Humidity Sensor Type: Capacitive

Weight: 22g

Length: 50cm